



Reorder No: 0304



Tech Specs:

Color	Greer
Fragrance	Faint
Form	Liquid
Phosphates	None
FlashPoint	212F
рН	12.5
Specific Gravity	1.03
Viscosity	Thin
Foam	Moderate
Biodegradable	100%
Shelf Life	1 Year

Available Packages	
0304-275	275 Gallon Tote
0304-55	55 Gallon Plastic Drum
0304-30	30 Gallon Plastic Drum
0304-15	15 Gallon Plastic Drum
0304-5.25	2x2.5 Gallon Jugs
0304-5	5 Gallon Plastic Pail
0304-4	4 Gallon Case
0304-2L	4x2Liter EZ Fill

Indy LF Low Foaming Floor Cleaner

Use: Floor Cleaning

What is Indy LF?

A low foaming floor cleaner that is perfect for removing the toughest soils. It has been fortified with cutting edge low foaming detergents to cut through the heavy grease and soil deposits. It has been designed for use in applications where high foaming is commonly a problem. This perfect blend of detergents will penetrate soils and grease, leaving floors bright and shiny. This versatile product can be used in a wide variety of applications, ranging from auto scrubbers to mopping.

Benefits:

- Removes the heaviest soils.
- Leaves floors bright and shiny.
- Low foam formula makes it perfect for use in auto scrubbers and rotary machines.
- Fortified with Sodium Hydroxide.
- Removes heavy grease and oils from deep cracks and imperfections in almost any floor.

Directions For Use:

Before using, make sure that the desired surface is cool to prevent early evaporation. Read MSDS and test in a small inconspicuous area. For professional use only by trained personnel.

Dilute 50-60:1 for light soils , 40:50-1 for moderate soils, 20-40:1 for heavy soils.

FLOOR SCRUB MACHINES:

Equip machine with aggressive brushes such as steel wire and fill reservoir with cleaner. Double-scrub procedure will give best results. Lay down solution with scrubbing action and allow solution to remain on surface 5 minutes - then lower squeegee blade, scrubbing again and pick up. CONVENTIONAL ROTARY FLOOR MACHINE:

Equip machine with aggressive brush such as steel wire. Spray, mop or spread cleaner on surface. Scrub area and allow to remain 5 minutes. Scrub again and pick up soiled solution with wet-vacuum or mop. MANUAL CLEANING:

Apply cleaner by spray mop or sponge and follow by aggressive double brushing or scrubbing. Pick up soiled solution with wet-vacuum, mop or wiping.